

3 Phase Auto Transformers

- Low loss iron core
- Slotted mounting holes for fast installation
- A full range of standard IP22 enclosures are available
- Fully Impregnated with tropic proof, anti-fungus varnish



415V Input – 380V Output		
VA	Input Volts	Output Volts
5kVA	415V	380V
10kVA	415V	380V
15kVA	415V	380V
20kVA	415V	380V
30kVA	415V	380V
40kVA	415V	380V
50kVA	415V	380V
60kVA	415V	380V
75kVA	415V	380V
100kVA	415V	380V

415V Input – 200V Output		
VA	Input Volts	Output Volts
5kVA	415V	200V
10kVA	415V	200V
15kVA	415V	200V
20kVA	415V	200V
30kVA	415V	200V
40kVA	415V	200V
50kVA	415V	200V
60kVA	415V	200V
75kVA	415V	200V
100kVA	415V	200V